



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Robert L. Morgan  
Executive Director

Lowell P. Braxton  
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

(801) 538-5340 telephone


(801) 359-3940 fax

(801) 538-7223 TTY

www.nr.utah.gov

June 13, 2003

TO: Minerals File

FROM: Lynn Kunzler, Senior Reclamation Biologist 

RE: Site Inspection, Lanny Jensen, Cream Time Quarry, S/039/009, Sanpete County, Utah

Date of Inspection: May 20, 2003  
Time of Inspection: 10:30 a.m.  
Conditions: clear  
Participants: Marilyn Jensen, Operator; John Blake, SITLA; and Lynn Kunzler, DOGM

**Purpose of Inspection:** To document site conditions.

#### Getting to the Site:

This quarry is located approximately 3 miles due south of Mayfield, Utah. The Cream Time Quarry is adjacent to the road. Phyllis Bown's Mayfield Quarry (S/039/011) is adjacent to this quarry on the eastern side.

#### Observations:

This quarry has not been operated since the death of Lanny Jensen. His wife, Marilyn and son, Zack have been trying to make arrangements to have the site reclaimed. On May 6, 2003, the Division received (from the Jensen's) an E-mail message with photos, claiming that Danny Bown was digging on their permit area. This inspection was coordinated with John Blake of SITLA, to investigate these claims.

Upon arrival at the site it was noted that some of the permit area markers were no longer standing, that had been placed between the Cream Time Quarry and the Mayfield Quarry in June, of 2001. Visually, it looked as if the active quarry operations were indeed on the Jensen permit area. Using the GPS data logger, we surveyed the line of disturbance between the two operations. Photos were taken along the permit area boundary line to document the disturbance in relation to the permit area.

#### Conclusions and Recommendations:

Results of the GPS survey show that a Mayfield Quarry has encroached approximately 0.44 acres onto the Cream Time Quarry, based on the location of the boundary markers that had been established in 2001. However, this encroachment is less than 0.1 acres based on the lease boundary between the two sites. It was also determined that the nature of disturbance is only overburden materials

Page 2  
Site Inspection  
S/039/009  
June 13, 2003

that have been placed on the Cream Time Quarry. There was no evidence that others have removed material from the Cream Time Quarry.

Currently, the Division and SITLA are working on an agreement with the Bown's in which they would complete the reclamation of the Cream Time Quarry by allowing them to use their excess overburden (one time) to complete the regrading portion and not apply this acreage to their permit. This appears to be a win-win proposal for all involved. The Division is currently working on a final draft of this proposal for approval.

jb  
O:\M039-Sanpete\S0390009-creamtime\inspections\insp-05202003.doc